

City of Detroit  
Department of Recreation Performance Audit  
Exhibit 8 – Pittsburgh

**Overall Evaluation – Very Good Condition**

- Safe and appealing.
- Equipment is well maintained, either newer plastic equipment or painted metal equipment.
- Safety surfacing under and around the equipment.
- Very little debris in the playground area.
- Neat and defined for functionality.



Ammon Center Playground had nice, well-maintained equipment with shock absorbent safety surfacing.

City of Detroit  
Department of Recreation Performance Audit  
Exhibit 8 – Pittsburgh



Frick Park playground had well-maintained equipment and shock absorbent surfaces below and around the equipment.



Armstrong Park had all swings, painted equipment and safety surfaces beneath and around the swing set.